Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name:

Work Order Type: Weatherization

Audit Name: MADISON

CLIENT INFORMATION

Client Name:

Address:

Client ID:

Alt. Client ID: 16016SW-0781

AGENCY INFORMATION

Agency: SWHRA

Agency Phone: (731) 989-5111

Fax:

Address: 1574 White AVE

Henderson, TN

Email Address:

Agency Contact: Murley, Rickey

Work Phone: Cell Phone: Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-422-4822

Client Name: Client ID: Work Order (Bid Form)

DOE Weatherization Assistant

Alt. Client ID: 16016SW-0781

Work Order Name:

Report Run On: 5/20/2010

Version 8.5.0

Page 1 of 3

Measures

Measure 1 Rep	Components				Inspected				
Comment									
				Estimated			Actual	T-4-1	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Windows	New prime window	Each	1					and should state the property of	
2 Labor	Labor	Each					The state of the s		
Other Detail				11.11]			
			Measur	e Sub Total:			Sub Total:		
Measure 2 Atti Comment	c Ins. R-30	Components A1				Inspected			
				Estimated			Actual		
# Material/Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	Attic Insulation - Blown Cellulose - R-30	SqFt	990						
2 Labor	Labor	Each	990	7777			V 100 100 100 100 100 100 100 100 100 10		
Other Detail						, [
					#14 / 15 P T T T T T T T T T T T T T T T T T T]		and the second s	
		Measure Sub Total:			Sub Total:				
				-					

Client Name:

Client ID: Alt. Client ID: 16016SW-0781

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/20/2010

DOE Weatherization Assistant Version 8.5.0

Page 2 of 3

Measure 3 CO Monitor is Needed Comment		Components				Inspected		
			Estimated			Actual		
# Material/Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	CO monitor	Each	1					
2 Labor	Labor	Hour	1					
Other Detail			Measur	e Sub Total:			Sub Total:	
Field Notes:	·							
		Work O	rder Gra	and Total:		Gran	nd Total:	

Client Name:

Client ID:

Alt. Client ID: 16016SW-0781

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/20/2010

DOE Weatherization Assistant

Version 8.5.0 Page 3 of 3